
Inductive sensor magnetic field immune Bi10-Q14-ADZ32X2/S34





Туре	Bi10-Q14-ADZ32X2/S34 4256225	
Ident-No.		
Rated operating distance Sn	10 mm	
Mounting condition	flush	
Assured sensing range	(0,81 x Sn) mm	
Correction factors	$St37 = 1$, $V2A \sim 0.7$, $Ms \sim 0.4$, $AI \sim 0.3$	
Repeatability	2 %	
Temperature drift	± 10 %	
Hysteresis	3 15 %	
Ambient temperature	-25+ 70 °C	
Operating voltage	20 250VAC	
Operating voltage	10 300VDC	
AC rated operational current	100 mA	
DC rated operational current	100 mA	
Frequency	50 60 Hz	
Residual current	1.7 mA	
Rated insulation voltage	1.5 kV	
Surge current	1 A (10 ms max. 5 Hz)	
Short-circuit protection	yes / latching	
Voltage drop at I _e	6V	
Wire breakage / Reverse polarity protection	yes / complete	
Output function	2-wire, normally open	
Smallest operating current I _m	≥ 3 mA	
Switching frequency	0.02 kHz	
Housing	rectangular, Q14	

52 x 30 x 14 mm

cable

2 x 0.34mm²

55 Hz (1 mm)

30g (11 ms) IP67

LED green

LED red


plastic, PBT-GF30-V0

plastic, PBT-GF30-V0

Ø 5.2, LifYY-11Y, PUR, 2 m

- rectangular, height 14mm
- top active face
- Plastic, PBT-GF30-V0
- magnetic field immunity (welding resistance) to DC and AC fields
- AC 2-wire, 20...250 VAC
- 2-wire DC, 10...300 VDC
- normally open
- cable connection

Wiring diagram



Functional principle

Inductive sensors are designed for wear-free and non-contact detection of metal objects. For this purpose they use a high-frequency electro-magnetic AC field that interacts with the target. With inductive sensors, this field is generated by an LC resonant circuit with a ferrite core coil. Magnetic field sensors incorporate a special ferrite core which makes them immune to magnetic AC and DC fields. They may thus be used in welding applications.

Dimensions

Connection

Cable quality
Cable cross section:

Housing material

Material active face

Vibration resistance

Degree of protection

Display switch state

Operating voltage display


Shock resistance


• Edition: • 08.11.2008

Inductive sensor magnetic field immune Bi10-Q14-ADZ32X2/S34



Mounting instructions	minimum distances
Distance D	1,5 x B
Distance W	3 x Sn
Distance S	1 x B
Distance G	6 x Sn
Width of the active face B	30 mm







Edition: • 08.11.2008

Inductive sensor magnetic field immune Bi10-Q14-ADZ32X2/S34



Accessories

Type code	Ident- No.	Short text	Dimension drawing
MW-Q14/Q20	6945006	mounting bracket; material VA 1.4301	0.5 oc. 5
MH-Q14	6950011	for mounting with active face downwards	Ø 8,7 6+0,2 Ø 4,3